ABSTRACT

Systems and methods are disclosed to correct for image degraded signals on a liquid crystal display panel are disclosed. Panels that comprise a subpixel repeating group having an even number of subpixels in a first direction may have parasitic capacitance and other signal errors due to imperfect dot inversion schemes thereon. Techniques for signal correction and localizing of errors onto particular subpixels are disclosed.

FINNEGAN HENDERSON FARABOW GARRETT & DUNNER LLP

1300 I Street, NW Washington, DC 20005 202.408.4000 Fax 202.408.4400 www.finnegan.com